Boat Name: [illegible]

Boat Model: [illegible]

Customer: Paul P

16/10/2024

Report

Mainsail / Genoa / Staysail / Light Genoa control and repairs :

Mainsail - Luff tape was changed. leech tape was changed 8 meters, worn batten-boxes has been changed.
Head side of the sail was completely sewn and other rip repairs has been made.

Genoa - UV seams were completely renewed, Luff tape was repaired, velcro on the cleat covers were changed, tell tales were changed. Head / tack / clew webbing seams were renewed and hand stitches were re-sewn.

Self Tacking Jib – UV seams has been renewed completely. New dacron reinforcement from clew corner's UV edge has been made and clew corner's UV has been repaired. Head / tack / clew webbing seams renewed. Cleat cover Velcro has been changed.Uv Protection must be Wider +20cm

Light Genoa - Lufftape has been changed, UV seams were completely renewed. Head and clew webbing changed. Reinforcement dacron and UV were put on the lower parts. Webbing hand stitches were made. Cleat cover velcro was changed. Seam repairs were made.

General conditions of the sails are:

Mainsail : OK, Heavy Duty, With the new sail it is possible to make it square-top.

Genoa : OK, Heavy Duty, With the new sail it is possible to make it higher square meter.

Self – Tacking Jib : Heavy duty, needs to be changed firstly among the all sails, can last 2-3 years more. With the new sail it is possible to make it higher square meter.

Light Genoa : OK, Heavy Duty, With the new sail it is possible to make it higher square meter.

***All Seams Use Dyneema Line**

Total Price : 1285 € + VAT

Best Regards

[illegible] Sails Group
[illegible] Marine Ltd.
Haci Güven
+90 [illegible]

MARİNE TUR. TİC. İHR.İTH. LTD. ŞTİ.
Çamdibi Mah. 284 Sk. No: 35/C Marmaris/MUĞLA
Marmaris V.D.H.No: [illegible] Gsm: [illegible]
Mersis No: [illegible] Tic.Sic.No: Marmaris/11267
E-mail: [illegible] Web: [illegible]

[illegible] Sails Group
Simple Marine Ltd.
Şeref Özsoy
+90 [illegible]